


## 7210 Ratchet spare parts sets for torque wrenches No 721

| code              | No                    | Content                                                                                                                                                        | Δg<br>g |
|-------------------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| <b>59 19 1005</b> | <b>7210/5</b>         | For ratchet/torque wrench No 721/5, 721/5 Quick:<br>1 pinion, 1 pawl, 1 switch-over button and pin,<br>1 ball, 2 compression springs, 2 screws                 | 53      |
| <b>19040000</b>   | <b>5120 + 7210/15</b> | For ratchet/torque wrench No 721/15, 721/15 Quick, 721/20, 721/20 Quick:<br>1 pinion, 1 pawl, 1 lever, 1 lever pin, 1 ball,<br>2 compression springs, 2 screws | 127     |
| <b>59 19 1030</b> | <b>7210/30</b>        | For ratchet/torque wrench No 721/30, 721/30 Quick:<br>1 pinion, 1 pawl, 1 lever, 1 lever pin, 1 ball,<br>2 compression springs, 2 screws                       | 134     |
| <b>59 19 1080</b> | <b>7210/80</b>        | For ratchet/torque wrench No 721Nf/80, 721Nf/100, 735/80, 735/100:<br>1 pinion, 2 pawls, 2 spring contact points, 2 compression springs                        | 443     |

## 70V Square drive units

• for torque wrenches and insert tools



502 1/2



70V 16

| code            | size           | for No                                                           | a<br>" | b<br>" | L<br>mm | Δg<br>g |  |
|-----------------|----------------|------------------------------------------------------------------|--------|--------|---------|---------|---------------------------------------------------------------------------------------|
| <b>59010001</b> | <b>1</b>       | 71...V/1                                                         | 1/4    | 1/4    | 17.5    | 5       | 5                                                                                     |
| <b>59010014</b> | <b>11</b>      | 734/4                                                            | 3/8    | 1/4    | 22      | 12      | 5                                                                                     |
| <b>59010003</b> | <b>3</b>       | 734/5                                                            | 3/8    | 3/8    | 25.8    | 17      | 5                                                                                     |
| <b>59010005</b> | <b>5</b>       | 734/10                                                           | 3/8    | 1/2    | 30      | 28      | 5                                                                                     |
| <b>59010011</b> | <b>502 1/2</b> | 720/30; 734/20                                                   | 1/2    | 1/2    | 33.5    | 40      | 5                                                                                     |
| <b>59010007</b> | <b>7</b>       | 721/30, 721/30 Quick                                             | 1/2    | 1/2    | 44.3    | 52      | 5                                                                                     |
| <b>59010008</b> | <b>8</b>       | 734/40                                                           | 3/4    | 3/4    | 52.2    | 138     | 5                                                                                     |
| <b>59010015</b> | <b>12</b>      | 720Nf/80; 721Nf/80+100; 734/80; 734/100; 735/80; 735/100         | 3/4    | 3/4    | 65      | 179     | 1                                                                                     |
| <b>59010016</b> | <b>16 *</b>    | 720Nf/80; 721Nf/80+100; 734/40; 734/80; 734/100; 735/80; 735/100 | 3/4    | 3/4    | 88      | 240     | 1                                                                                     |

\* extra-long, firmly locked, so usable from both sides