


Coordinated – down to the last detail. STAHLWILLE calibration systems.



	No for full system	7706-8 PC	7706-9 PC	7706-10 PC	7706-11 PC
	Code	96 52 10 68	96 52 10 69	96 52 10 70	96 52 10 74
	Weight in kg	14.2	67.6	70.6	108.4
	Range N-m	1-10	2-100	2-1000	20-3000
	Mechanical loader	-	No 7791	No 7791	No 7792
	»Stand alone« test attachment for torque screwdrivers	No 7790	-	-	-
	Extension	-	-	No 7791-1	No 7792-1
	Laboratory transducers	No 7728-1S (1-10 N-m)	No 7728-2 (2-20 N-m) No 7728-10 (10-100 N-m)	No 7728-2 (2-20 N-m) No 7728-10 (10-100 N-m) No 7728-40 (40-400 N-m) No 7728-100 (100-1000 N-m)	No 7728-20 (20-200 N-m) No 7728-100 (100-1000 N-m) No 7728-300 (300-3000 N-m)
	USB adapter	No 7757-1	No 7757-1	No 7757-1	No 7757-1
	Jack cable	No 7751	No 7751	No 7751	No 7751
	Cable to No. 7728 (transducer to USB adapter)	No 7751-1	No 7751-1	No 7751-1	No 7751-1
	Square drive adapters	No 431 (3/8" □ x 1/4" ■)	No 431 (3/8" □ x 1/4" ■) No 409M (1/4" □ x 3/8" ■)	No 7787 (1/4" □ x 3/4" ■) No 7788 (3/8" □ x 3/4" ■) No 7789 (1/2" □ x 3/4" ■) No 409M (1/4" □ x 3/8" ■)	No 7787 (1/4" □ x 3/4" ■) No 7788 (3/8" □ x 3/4" ■) No 7789 (1/2" □ x 3/4" ■) No 7789-2 (3/4" □ x 1 1/2" ■) No 7789-3 (1" □ x 1 1/2" ■) No 7789-4 (1/4" □ x 1 1/2" ■) No 7789-5 (3/8" □ x 1 1/2" ■)
	Calibrating square drive insert tools	-	No 734K/4 (1/4" ■) No 734K/5 (3/8" ■)	No 734K/4 (1/4" ■) No 734K/5 (3/8" ■) No 734K/20 (1/2" ■) No 734K/40 (3/4" ■)	No 734K/4 (1/4" ■) No 734K/5 (3/8" ■) No 734K/20 (1/2" ■) No 734K/40 (3/4" ■)
	Adapters	No 3115 (1/4" ■ x 1/4" ● E 6.3) No 3115/1 (1/4" ■ x 1/4" ● C 6.3)	-	-	-
	Calibration software	TORKMASTER	TORKMASTER	TORKMASTER	TORKMASTER
	DAkkS calibration certificates	1	2	4	3