


Spare parts

7210 Ratchet spare parts sets for torque wrenches No 721

Code	No	Content	ΔΔ g
59 19 10 05	7210/5	For ratchet/torque wrench No 721/5, 721/5 Quick: 1 pinion, 1 pawl, 1 switch-over button and pin, 1 ball, 2 compression springs, 2 screws	53
19 04 00 00	5120 + 7210/15	For ratchet/torque wrench No 721/15, 721/15 Quick, 721/20, 721/20 Quick: 1 pinion, 1 pawl, 1 lever, 1 lever pin, 1 ball, 2 compression springs, 2 screws	127
59 19 10 30	7210/30	For ratchet/torque wrench No 721/30, 721/30 Quick: 1 pinion, 1 pawl, 1 lever, 1 lever pin, 1 ball, 2 compression springs, 2 screws	134
59 19 10 80	7210/80	For ratchet/torque wrench No 721Nf/80, 721Nf/100, 735/80, 735/100: 1 pinion, 2 pawls, 2 spring contact points, 2 compression springs	448

70V Square drive units

for torque wrenches and insert tools.



502 1/2



70V 16

Code	size	for No	a "	b "	L mm	ΔΔ g	
59 01 00 01	1	71...V/1	1/4	1/4	17.5	5	5
59 01 00 14	11	734/4	3/8	1/4	22	12	5
59 01 00 03	3	734/5	3/8	3/8	25.8	17	5
59 01 00 05	5	734/10	3/8	1/2	30	28	5
59 01 00 11	502 1/2	720/30; 734/20	1/2	1/2	33.5	39	5
59 01 00 07	7	721/30	1/2	1/2	44.3	52	5
59 01 00 08	8	734/40	3/4	3/4	52.2	138	5
59 01 00 15	12	720Nf/80; 721Nf/80+100; 734/80; 734/100; 735/80; 735/100	3/4	3/4	65	179	1
59 01 00 16	16*	720Nf/80; 721Nf/80+100; 734/40; 734/80; 734/100; 735/80; 735/100	3/4	3/4	88	240	1

* extra-long, firmly locked, so usable from both sides

Spares for MULTIPOWER

SR290-393 Sun wheel with overload cutout



Code	No	for No	ΔΔ g
59 03 08 00	SR300-800	MP300-800	45
59 03 13 50	SR300-1350	MP300-1350	106
59 03 20 00	SR300-2000	MP300-2000	120
59 03 30 00	SR300-3000	MP300-3000	130
59 03 50 00	SR300-5000	MP300-5000	127
59 30 00 39	SR290N	STW 290N	41
59 30 00 67	SR295N	STW 295N	95
59 30 00 68	SR391N	STW 391N	95
59 30 00 69	SR392N	STW 392N	105
59 30 00 70	SR393N	STW 393N	105

 Made in
Germany