



Complete calibration systems with matched components



Mechanical base unit



Transducer laboratory



Cable
No 7751-1



USB adaptor No 7757-1



USB adaptor



PC/Printer – not included
in the delivery



Calibration systems No	7706-8 PC	7706-9 PC	7706-10 PC	7706-11 PC
Code	96 52 10 68	96 52 10 69	96 52 10 70	96 52 10 74
Weight/kg	14,2	67,6	70,6	108,4
Range/N-m	1-10	2-100	2-1000	20-3000
Mechanical loader	-	No 7791	No 7791	No 7792
Stand alone test attachment for torque screwdrivers	No 7790	-	-	-
Extension unit	-	-	No 7791-1	No 7792-1
Transducer laboratory	No 7728-1S (1-10 N-m)	No 7728-2 (2-20 N-m) No 7728-10 (10-100 N-m)	No 7728-2 (2-20 N-m) No 7728-10 (10-100 N-m) No 7728-40 (40-400 N-m) No 7728-100 (100-1000 N-m)	No 7728-20 (20-200 N-m) No 7728-100 (100-1000 N-m) No 7728-300 (300-3000 N-m)
USB adaptor	No 7757-1	No 7757-1	No 7757-1	No 7757-1
Jack cable	No 7751	No 7751	No 7751	No 7751
Cable for No 7728 (connection between transducer and USB adaptor)	No 7751-1	No 7751-1	No 7751-1	No 7751-1
Square drive adaptor	No 431 (3/8"  x 1/4" )	No 431 (3/8"  x 1/4" ) No 409M (1/4"  x 3/8" )	No 7787 (1/4"  x 3/4" ) No 7788 (3/8"  x 3/4" ) No 7789 (1/2"  x 3/4" ) No 409M (1/4"  x 3/8" )	No 7787 (1/4"  x 3/4" ) No 7788 (3/8"  x 3/4" ) No 7789 (1/2"  x 3/4" ) No 7789-2 (3/4"  x 1 1/2" ) No 7789-3 (1"  x 1 1/2" ) No 7789-4 (1/4"  x 1/2" ) No 7789-5 (3/8"  x 1/2" )
Calibrating square drive insert tools	-	No 734K/4 (1/4" ) No 734K/5 (3/8" )	No 734K/4 (1/4" ) No 734K/5 (3/8" ) No 734K/20 (1/2" ) No 734K/40 (3/4" )	No 734K/4 (1/4" ) No 734K/5 (3/8" ) No 734K/20 (1/2" ) No 734K/40 (3/4" )
Adaptors	No 3115 (1/4"  x 1/4"  ● E 6,3) - No 3115/1 (1/4"  x 1/4"  ● C 6,3) -	-	-	-
Calibration software	TORKMASTER	TORKMASTER	TORKMASTER	TORKMASTER
DAkKS calibration certificates	1	2	4	3