



TCS 40/41/44/8




TCS



175 x 350 x 45 mm, 33 pieces

Code		g
96 83 02 17		715
	No 40	1/4"  sizes 5; 5.5; 6; 7; 8; 9; 10; 11; 12; 13; 14 mm
	No 41K	1/4"  0.6 x 3.5; 1.0 x 5.5; 1.2 x 8 mm
	No 44K	1/4"  3; 4; 5; 6; 8 mm
	No 44P	1/4"  sizes 1; 2; 3; 4
	No PZ1221 No PZ1222	1/4"  size 1 1/4"  size 2
	No 400	1/4"  150 mm
	No 404	1/4"  116 mm
	No 405/2	1/4"  54 mm
	No 405/6	1/4"  150 mm
	No 407	1/4"  38 mm
	No 409	3/8"  1/4" 
	No 412	1/4"  
	No 415	1/4" 



TCS 40/35/9




TCS



175 x 350 x 40 mm, 44 pieces

Code		g
96 83 06 01		1045
	No 40	1/4"  sizes 5; 5.5; 6; 7; 8; 9; 10; 11; 12; 13; 14 mm
	No 40L	1/4"  sizes 4; 4.5; 5; 5.5; 6; 7; 8; 9; 10; 11; 12; 13 mm
	No 41K	1/4"  0.6 x 3.5; 1.0 x 5.5; 1.2 x 8 mm
	No 44K	1/4"  3; 4; 5; 6; 8 mm
	No 44P	1/4"  sizes 1; 2; 3; 4
	No 400	1/4"  150 mm
	No 404	1/4"  116 mm
	No 405/2 No 405/4	1/4"  54 mm 1/4"  100 mm
	No 405/6	1/4"  150 mm
	No 407	1/4"  38 mm
	No 412	1/4"  
	No 415	1/4" 
	No 409	3/8"  1/4" 


TCS 4008/8/52



TCS



175 x 350 x 50 mm, 60 pieces

Code		g
96 83 87 73		665
	No 412	1/4"  
	No 412/1	1/4"  10 mm 
	No 442	1/4"  3/8" 
	No 1200/1	1/4"  
	No 3825/1	1/4"  
	No 3115/1	1/4"  
	No 4008-1	1/4" 
	No 4008-2	1/4" 
	No 1300 No 1301 No 1302 No 1303 No 1304	size 3 mm (2x) size 4 mm (2x) size 5 mm (2x) size 6 mm (2x) size 8 mm (2x)
	No 1220 No 1221 No 1222 No 1223	size 0 (2x) size 1 (2x) size 2 (2x) size 3 (2x)
	No PZ1221 No PZ1222 No PZ1223	size 1 (2x) size 2 (2x) size 3 (2x)
	No 1414 No 1415 No 1416 No 1417 No 1419 No 1420	size T10 (2x) size T15 (2x) size T20 (2x) size T25 (2x) size T30 (2x) size T40 (2x)
	No 1440 No 1441 No 1442 No 1443 No 1445 No 1446	size T10 (2x) size T15 (2x) size T20 (2x) size T25 (2x) size T30 (2x) size T40 (2x)
	No 1161 No 1163 No 1165 No 1166/1	size 0.5 x 4.0 mm size 0.6 x 4.5 mm size 0.8 x 5.5 mm size 1.2 x 6.5 mm

Tool Control System

The safety inlay system

- Designed to fit our Tool Trolleys and Tool Boxes
- With yellow signal cut-outs to show whether all tools are in their places



TCS